


*Well Not Any More*

**“OH,  
SHEET!”**




**Oh, Sheet! Moments:  
The Importance of Inspection Equipment**



# Manufacturing Errors ... They Happen!

- It Happens ... But It's Preventable
- Small Manufacturing Errors = Costly Problem





# Protect Your Bottom, and Your Bottom Line From ...

Unexpected Labor Charges

**“OH, SHEET!”**

Costly Repairs on High-Dollar Machinery

Loss Profits from Downtime

Scrap Due to Defective Parts

Refused Shipment

**Scrap is  
expensive!**





**PRIME  
CONTROLS**  
*Metal Sensing Solutions*



# Oh, Sheet! Moments

## QUALITY CONTROL TIPS FOR CANMAKERS






# Tip #1: Be Sure to Deploy Double Sheet Detection

- Essential Part of Quality Control
- Failure to Detect Can be Costly
- Made Up of Control + Single or Dual Probe
- Full Range of Metal Types, Thickness, Contact vs. Non-Contact

## Ideal Machinery:

- Sheet Feeder
- Slitter Tables
- Destackers
- Metal Sheet Printing Press
- End of Arm Tooling






# Tip #2: Watch for Double Shells & Missing Tab

- Double Shell & Missing Tab Detection System: Vital to Can End Makers
- Prevents Double Shells Entering Conversion Press
- Verifies Tab on Outfeed of Press
- Double End Detectors Found on Curling Process
- Magnetic Conveyors Throughout Plant





# Tip #3: Don't Go Without Leak Detection

- Produced at High Speeds – No Room for Error
- Prevent Defective Products
- Light or Air Used to Detect Defects
- End Light System Detects 5 Micron & Below Holes – Speeds of 1,100 EPM




**PRIME**  
**CONTROLS**  
Metal Sensing Solutions



# Oh, Sheet! Moments

## How Can QC Solutions Save Your Bottom Line?

Avoiding Oh, Sheet! Moments



**PRIME  
CONTROLS**  
*Metal Sensing Solutions*



# Costly Moments from the Field

Issue: Double Blank of Metal Entered into Press


Cost: \$180,000 Worth of Repairs

Solution: Small Investment in Double Sheet Detection System at the Infeed

*Ultimately Preserving the Press*



**PRIME  
CONTROLS**  
Metal Sensing Solutions



# Costly Moments from the Field


Issue: Cracks in Cans for Oil Filters

Result: Unable to Sell Defective Product

Solution: Custom Light Testing System Detecting the Smallest Cracks

***Able to Produce and Sell Quality Product with Confidence.***





# Costly Moments from the Field

Issue: Obsolete Product Failure

Result: Line was Down from Not Being Able to Test Cans

Solution: Received New System the Next Day

***Customer Back Up and Running Quickly.***



**IN STOCK**





# Costly Moments from the Field

Issue: Two Ends Seamed onto a Can


Result: Can Exploded and Caused Slight Injury. Entire Shipment of Thousands Cans Returned

Solution: Installed Double End Detection System




*Peace of Mind of Quality Product.*






# Oh, Sheet! Moments

**How Are You Protecting  
Your Machinery?**



**PRIME  
CONTROLS**  
*Metal Sensing Solutions*



# Help Us by Writing Down Your "Oh, Sheet!" Moment.

**BE A HERO**

**SHARE YOUR "OH, SHEET!" STORY...**

**...AND WIN!!!**  
**#ohsheetmoment**





# Thank You!

If you have any questions or would like additional information,  
Please use contact information below:

**WORLD HEADQUARTERS**

*Dayton, Ohio – USA*

**+1-937-435-8659**

***[vip@primecontrols.com](mailto:vip@primecontrols.com)***

***[www.primecontrols.com](http://www.primecontrols.com)***



**PRIME  
CONTROLS**  
*Metal Sensing Solutions*